Modernisierung/Instandsetzung eines Wohnhauses

Soldiner Str. 10, Berlin

(function() { var sliderElement = [].slice.call(document.getElementsByClassName('mod_rocksolid_slider'), -1)[0]; if (window.jQuery && jQuery.fn.rstSlider) { init(); } else { document.addEventListener('DOMContentLoaded', init); } function init() { var $ = jQuery; var slider = $(sliderElement); slider.find('video[data-rsts-background], [data-rsts-type=video] video').each(function() { // Disable mejs for videos this.player = false; }); slider.rstSlider({"type":"slide","direction":"x","navType":"thumbs","scaleMode":"none","imagePosition":"top-left","centerContent":false,"random":false,"loop":false,"videoAutoplay":false,"autoplayProgress":false,"pauseAutoplayOnHover":true,"keyboard":true,"captions":false,"controls":true,"thumbControls":true,"combineNavItems":true,"visibleAreaAlign":0.5,"gapSize":"0%","thumbs":{"width":"240","height":"460","controls":true,"slideMaxCount":1,"slideMinSize":180,"slideMaxSize":180,"rowMaxCount":3,"rowMinSize":180,"prevNextSteps":1,"gapSize":20,"direction":"y"}}); // Fix missing lightbox links $(function() { if (!$.fn.colorbox) { return; } var lightboxConfig = { loop: false, rel: function() { return $(this).attr('data-lightbox'); }, maxWidth: '95%', maxHeight: '95%' }; var update = function(links) { links.colorbox(lightboxConfig); }; slider.on('rsts-slidestart rsts-slidestop', function(event) { update(slider.find('a[data-lightbox]')); }); update(slider.find('a[data-lightbox]')); }); } })();

(function() { var sliderElement = [].slice.call(document.getElementsByClassName('mod_rocksolid_slider'), -1)[0]; if (window.jQuery && jQuery.fn.rstSlider) { init(); } else { document.addEventListener('DOMContentLoaded', init); } function init() { var $ = jQuery; var slider = $(sliderElement); slider.find('video[data-rsts-background], [data-rsts-type=video] video').each(function() { // Disable mejs for videos this.player = false; }); slider.rstSlider({"type":"slide","direction":"x","navType":"thumbs","scaleMode":"none","imagePosition":"top-left","centerContent":false,"random":false,"loop":false,"videoAutoplay":false,"autoplayProgress":false,"pauseAutoplayOnHover":true,"keyboard":true,"captions":false,"controls":true,"thumbControls":true,"combineNavItems":true,"visibleAreaAlign":0.5,"gapSize":"0%","thumbs":{"width":"240","height":"460","controls":true,"slideMaxCount":1,"slideMinSize":180,"slideMaxSize":180,"rowMaxCount":3,"rowMinSize":180,"prevNextSteps":1,"gapSize":20,"direction":"y"}}); // Fix missing lightbox links $(function() { if (!$.fn.colorbox) { return; } var lightboxConfig = { loop: false, rel: function() { return $(this).attr('data-lightbox'); }, maxWidth: '95%', maxHeight: '95%' }; var update = function(links) { links.colorbox(lightboxConfig); }; slider.on('rsts-slidestart rsts-slidestop', function(event) { update(slider.find('a[data-lightbox]')); }); update(slider.find('a[data-lightbox]')); }); } })();

Leistungen

- Gebäudeplanung/Architektur
- Planung technische Ausrüstung

Zeitraum:	2016 - 2017
Anzahl WE/GE:	8/2
Bauherr:	GESOBAU AG

Maßnahmen

- Hüllensanierung
- Strangsanierung
- Schadstoffsanierung
- Leer-WE-Sanierung
- Freianlagen